



BIOS Update Release Notes

**PRODUCTS: D2700MUD, D2700DC, D2500HN, D2550DC2, D2550MUD2
(Standard BIOS)**

BIOS Version 0076 - MUCDT10N.86A.0076.2013.0618.1644

About This Release:

- Date: June 18, 2013
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1083
- PXE: v1.3.65

New Fixes/Features:

- Fixed issue where certain barcode reader does not work.

BIOS Version 0075 - MUCDT10N.86A.0075.2013.0427.1548

About This Release:

- Date: April 27, 2013
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1083
- PXE: v1.3.65

New Fixes/Features:

- Added support for ErP.

BIOS Version 0074 - MUCDT10N.86A.0074.2012.1207.0946

About This Release:

- Date: December 7, 2012
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1083
- PXE: v1.3.65

New Fixes/Features:

- Fixed issue where system hangs at POST code EB when a barcode scanner is connected.

BIOS Version 0073 - MUCDT10N.86A.0073.2012.1101.1638

About This Release:

- Date: November 1, 2012
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1083
- PXE: v1.3.65

New Fixes/Features:

- Added Eurostar* support.

*Other names and brands may be claimed as the property of others.

BIOS Version 0072 - MUCDT10N.86A.0072.2012.0808.1512

About This Release:

- Date: August 8, 2012
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1083
- PXE: v1.3.65

New Fixes/Features:

- Updated vBIOS to version 1083.

BIOS Version 0071 - MUCDT10N.86A.0071.2012.0612.1459

About This Release:

- Date: June 12, 2012
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1071
- PXE: v1.3.65

New Fixes/Features:

- Fixed security check issue.

BIOS Version 0070 - MUCDT10N.86A.0070.2012.0529.0930

About This Release:

- Date: May 29, 2012
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1071
- PXE: v1.3.65

New Fixes/Features:

- Fixed issue where Shift + Right arrow does not work in edit.com under DOS.
- Fixed issue where system hangs at POST code 5Ah when SATA-to-Compact Flash adapter without media is connected.
- Fixed issue with LAN behavior under DOS.
- Fixed issue where vBIOS does not get Pay-load EDID.
- Fixed issue with Fast Boot feature.

BIOS Version 0069 - MUCDT10N.86A.0069.2012.0323.1358

About This Release:

- Date: March 23, 2012
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1071
- PXE: v1.3.65

New Fixes/Features:

- Fixed issue where only 2.99GB usable memory is reported if system is populated with 4GB memory.
- Update vBIOS to revision 1071.

- Fixed issue where the panel power sequence control items in BIOS do not work properly.
- Updated to skip pressing enter key after warning message for following events: CMOS battery failure/ CMOS Checksum Error/ system date/time.

BIOS Version 0067 - MUCDT10N.86A.0067.2011.1227.1232

About This Release:

- Date: December 27, 2011
- vBIOS: 1053
- PXE: v1.3.65

New Fixes/Features:

- Fixed issue where PS/2 port does not work during POST or in BIOS setup.
- Fixed issue where the POST hotkey shows incorrectly if the logo is set to a 320x200 image.
- Fixed issue where Type 01 of Pre-Defined EDID in Setup is incorrect.

BIOS Version 0063 - MUCDT10N.86A.0063.2011.1129.1546

About This Release:

- Date: November 29, 2011
- vBIOS: 1053
- PXE: v1.3.65

New Fixes/Features:

- Removed "keyboard not found event" from BIOS.
- Fixed issue where parallel mode is always set to SPP when system resumes from S3.
- Fixed issue where certain 8GB USB flash drive is not bootable.
- Fixed issue where the default threshold value for VR Temperature in BIOS Setup does not match the threshold value in Intel Desktop Utilities.
- Unlocked "IGD Flat Panel" in Maintenance mode when "Flat Panel Configuration Changes" is set to Unlocked.
- Fixed issue where the BSU string WXGA (1280*1080) does not match BIOS setup specification.
- Updated VBIOS to version 1053.
- Fixed issue where the system hangs during S4 resume if populated with TPM and 2GB memory.
- Fixed issue where system hangs if powering on without any monitor connected.
- Fixed issue where LVDS is too dark at the minimal brightness level.
- Added HDD Password update for the latest HDD password specification.
- Changed Associated Fan Controller and Associated Fan Sensor from 0 to 1 and 2.
- Fixed issue where settings changed on the Set Sensor Threshold page of Intel Desktop Utilities do not persist.
- Improved the time from power on to splash screen.

*Other names and brands may be claimed as the property of others.

- Added support for USB optical drives in the F& flash update feature.
- Removed garbage character of 5V standby reading in Setup.
- Added support for Microsoft* OEM Activation 3.0.
- Removed power supervisor feature.

BIOS Version 0054 - MUCDT10N.86A.0054.2011.0927.1618

About This Release:

- Date: September 27, 2011
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1043
- PXE: v1.3.65

New Fixes/Features:

- Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries.
Copyright (c) 2012 Intel Corporation.

*Other names and brands may be claimed as the property of others.